

2nd Beeston Sea Scouts

Boat Maintenance report 2018 / 19

Trent

Now back on the water after maintenance over the winter

Repairs to transom completed, including new sculling notch, and additional stainless-steel strengthening fishplates fitted. Hardwood rubbing strips fitted to gun'als

'Boom up' cover (like Conwy's) completed and in use

Dart

No progress to date

Adaption for use as a work boat in hand

Have details of Plimsol line requirements

Conwy

After a season on the water, returned to Lilac Grove for inspection. Engine removed for annual service. Now back on water and fully operational

Canoe trailer

Brake problem now identified braking system overhaul progressing:-

Main Boat trailer – (Styx / Conway / Trent)

Hardwood pads fitted to hull support legs and refitted with stainless steel studs fabricated for purpose

Suitable doubling plates require fitting in way of new jockey wheel fixing bolts

Canoes

Need to fit skid-plates and centre thwart kits as required – materials already in stock

Inspection of new canoes / kayaks to be completed – but looking good so far